

Viper VP4300 Lite 2TB SSD Firmware Error Notice and Update Instructions

Patriot Memory has discovered thermal reporting errors with the VP4300 Lite's current firmware (H230407a). These errors are incorrectly displaying higher than actual temperatures within monitoring applications while temperature and performance are within normal specs. Due to this, the Patriot Memory team has worked with the flash controller manufacturer to prepare a firmware update set to correct the thermal information passed to monitoring applications.

This error is found to occur in VP4300 Lite 2TB SSD units with the following serial numbers:

022305291200001-022305291200500

In addition to this, all VP4300 Lite units released outside of the listed serial numbers will have the new firmware (H230407b) installed and should not experience thermal reporting errors. Patriot Memory does not recommend installing the update to any VP4300 Lite drives outside of the affected serial numbers listed.

For any additional questions, concerns or help from support, please contact Patriot Memory support and visit the Patriot Memory Warranty page at: https://www.patriotmemory.com/patriot-memory-warranties-and-rma

To update the firmware of the specified units, please follow the steps below:

Important Notice: Updating firmware can cause data loss; please back up drive data before updating.















